



**Angle-Arc® Manual Gouging Torch Parts**



**K4000**

**Hook-Up Kit & Parts**




**Torch Assembly Replacement Parts**

Item	Description	K4000
	<b>Complete Torch</b>	01-082-002
1	Insulators & Screws	94-433-183
2	Upper Insulator	N/A
3	Lower Insulator	N/A
4	Lever & Screw	94-476-066
5	Valve Bonnet	94-104-016
6	Bonnet Wrench	94-960-001
7	Bonnet Only	94-104-012
8	Spool & O-Rings	94-801-011
9	O-Ring (2 Reqd.)	94-710-036
10	Spool Only	94-801-010
11	Upper Arm	94-048-088
12	Head & Screw	94-378-368
13	Torch Body	94-103-206
14	Hinge Pin	94-632-094
15	Spring	94-800-077
16	Handle	94-370-163

Item	Description	Cat No.
	<b>Complete Hook-Up Kit</b>	94-463-045
1	Male Gouging Connector	94-170-181
2	Cable Boot Cap	94-105-027
3	4-WPC-R Connector	9425-1427
4	Pigtail Air Supply Hose	94-396-205

**Cable Assembly Replacement Parts**



Item	Description	K4000
	<b>7' (2.1m) Cable Assembly</b>	70-084-207
	<b>10' (3m) Cable Assembly</b>	70-084-210
1	Retainer Screw	94-170-182
2	O-Ring	SEE ABOVE
3	Connector	SEE ABOVE
4	Spring Washer	94-940-104
5	Flat Washer	94-940-103
6	Swivel Sleeve	N/A
7	Clamp (2 Required)	98-167-010
8	7' (2.1m) Conductor	96-130-263
8	10' (3m) Conductor	96-130-261
9	7' (2.1m) Cover	94-171-274
9	10' (3m) Cover	94-171-274
10	Insulating Boot	94-105-014
11	Female Connector	94-170-150